

| The Vicarage, 57 Sketty Road, Swansea. | | | | Survey Type > | | | Update Asbestos Survey | | | Initial Survey Date(s) > | | | | | | 08/09/2015 | | | | | | |
|--|----------------------------|----------------------|-------------|-----------------|---------------------------------------|-------------------------|------------------------|--|-----------------------------------|--------------------------|------------------|-----------|----------------------|--|--------------------------------|---|-------------------------|---|-------------------------|------------------------|---|----------------|
| 5575AS172 | | | | Register Type > | | | Final | | | Risk ratings | | | | | | Management Action | | | | | | |
| Report Section | Extrapolated from Site Ref | UPRN (if applicable) | Lab Ref | Site Ref | Area or room | Position | Component description | Material | Asbestos ID | Extent / approx quantity | ** Accessibility | ** Damage | ** Surface treatment | Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite) | Total Material Risk rating "A" | Total Priority Risk rating "B" - Score breakdown available on request | Total Risk Rating "A+B" |  | Last date ACM inspected | Last date ACM modified | Note | Licensed work? |
| G | | | NGAR5 850-3 | 5575AS17 2-005 | Second floor - Roof spaces 1 and 2 | Under roof coverings | Sarking felt | Bitumen roofing felts | Negative asbestos sample | 100SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 08/09/15 | | | |
| H | | | | 5575AS17 2-004 | Ground floor - Kitchen and utility | Under two sink units | Bitumen pads | Bitumen coatings on metal | Discounted material (not sampled) | 4No | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 08/09/15 | | | |
| I | | | NGAR5 850-1 | 5575AS17 2-001 | Ground floor - External - Rear garden | One loose slate on path | Red slate | Cement - Fully comp flat sheet, tiles, slates & boards | Removed | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/12/25 | | Loose slate has now been removed prior to revisit 16/05/17 | |
| I | | | NGAR5 850-2 | 5575AS17 2-002 | External - Stores 1 and 2 | Roof coverings | Profiled sheet | Cement - Profiled sheets | Removed | 13SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/12/25 | | New roof on Stores 1 and 2 roof has been removed prior to revisit 16/05/17 | |
| I | 5575 AS17 2-002 | | | 5575AS17 2-003 | Garage | Roof coverings | Profiled sheet | Cement - Profiled sheets | Removed | 15SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/12/25 | | Garage has now been demolished so roof has been removed prior to revisit 16/05/17 | |
| I | 5575 AS17 2-001 | | | 5575AS17 2-006 | Roof | Roof coverings | Roof slate | Cement - Fully comp flat sheet, tiles, slates & boards | Removed | 100SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/12/25 | | Main roof looks new, old roof removed prior revisit 16/05/17 | |