

49 Gwendoline Street, Tynewydd. 2220AS10						Survey Type >		Type 2		Initial Survey Date(s) >						15/12/2009						
Report Section	Extrapolated from Site Ref	UPRN	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	Accessibility	Damage	Surface treatment	Risk ratings			Management Action					
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation				Last date ACM inspected	Last date ACM modified
G		03GWN 04900	91558/B494-1	2220AS10-001	Ground floor - Lounge/diner and kitchen	Ceilings	'Artex' - 'Circle'	Textured coatings & joint compound	Negative asbestos sample	26SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09				
G			91558/B494-2	2220AS10-002	Ground floor - Hall	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09				
G			91558/B494-3	2220AS10-003	Ground floor - Kitchen	Underside sink top and drainer	Bitumen pads	Bitumen coatings on metal	Negative asbestos sample	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09				
G			91558/B494-4	2220AS10-004	First floor - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	29SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09				
G			91558/B494-5	2220AS10-006	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Negative asbestos sample	50SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09				
H				2220AS10-005	First floor - Bathroom	Floor	Black cushion sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09				