

35 Ty Isaf Road, Gelli, Pentre.					Survey Type >			Management		Initial Survey Date(s) >							05/07/2010				
2220AS118										Risk ratings							Management Action				
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	* Accessibility	* Damage	* Surface treatment	Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
Recommendation																					
G		10TYSO3 500	00005/B736-1	2220AS11 8-001	LGF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	24SM	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/10			
G		10TYSO3 500	00005/B736-2	2220AS11 8-004	GF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	24SM	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/10			
G		10TYSO3 500	00005/B736-3	2220AS11 8-005	FF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	24SM	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/10			
H		10TYSO3 500		2220AS11 8-002	LGF - Kitchen and hall	Floors	Grey vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	18SM	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/10			
H		10TYSO3 500		2220AS11 8-003	LGF - Kitchen	Underside sink top	Bitumen pad	Bitumen coatings on metal	Discounted material (not sampled)	1SM	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/10			
H		10TYSO3 500		2220AS11 8-006	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	40SM	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/10			