

Kitchen - 24 Mikado Street, Penygraig, Tonypandy.				Survey Type >		Refurbishment		Initial Survey Date(s) >						10/11/2020								
2220AS1300A				Register Type >		Final		Risk ratings						Management Action								
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
E				2220AS1300A-001	Kitchen	Above skimmed ceiling	N/A	NA (no access)	No access (Presumption)	9SM	NA	NA	NA	NA	NA	NA	NA	Re-evaluate if access obtained	10/11/20			
E				2220AS1300A-003	Kitchen	Beneath floor screed	N/A	NA (no access)	No access (Presumption)	9SM	NA	NA	NA	NA	NA	NA	NA	Re-evaluate if access obtained	10/11/20			
G		PHH18223-1		2220AS1300A-004	Kitchen	Under sink and drainer	Bitumen pads	Bitumen coatings on metal	Negative asbestos sample	Small Quants	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	10/11/20			
H				2220AS1300A-002	Kitchen	Floor covering	Blue sheet vinyl	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	9SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	10/11/20			

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.