

Bathroom - 66 Jones Street, Blaenclydach, Tonypanyd.					Survey Type >		Refurbishment		Initial Survey Date(s) >							19/01/2017						
2220AS132A					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			PHH11 16-1	2220AS13 2A-001	Bathroom	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/17			
H				2220AS13 2A-002	Bathroom	Wall above sink	Ceramic tiles	Other	Discounted material (not sampled)	1SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/17		Ceramic	
H				2220AS13 2A-003	Bathroom	Wall adjacent to landing and bedroom	Lining board	Insulating board	Discounted material (not sampled)	8SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/17			
H				2220AS13 2A-004	Bathroom	Bath panel	Lining board	Insulating board	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/17			

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.