

RHA Storage Buildings, Dunraven Street, Tonypanydy.					Survey Type >			Management		Initial Survey Date(s) >							20/04/2016												
2220AS1336																													
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Management Action				Licensed work?							
																													
																		Recommendation				Last date ACM inspected		Last date ACM modified		Note			
G			NGAR7 342-1	2220AS13 36-004	External	Low level brick work	Damp proof courses	Bitumen damp proof courses	Negative asbestos sample	34LM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	20/04/16										
H				2220AS13 36-001	Storage shed 1	Left hand side to top shelf	Ceiling tiles	Insulation board as ceiling tiles	Discounted material (not sampled)	8No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	20/04/16			New tiles							
H				2220AS13 36-002	Storage shed 2	To back wall top shelf underside sink and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	20/04/16			New sink							
H				2220AS13 36-003	Storage shed 2	To right hand side to felt rolls stood up	Flat roofing felt	Bitumen roofing felts	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	20/04/16			New rolls							
H				2220AS13 36-005	All areas	Under roof coverings	Plastic membrane	Bitumen roofing felts	Discounted material (not sampled)	65SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	20/04/16			Plastic							

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.