

Bathroom - 19 Balaclava Court, Penygraig, Tonypanydy.				Survey Type >		Update Asbestos Survey		Initial Survey Date(s) >							27/06/2019							
2220AS136A				Register Type >		Final		Risk ratings							Management Action							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
E				2220AS136A-004	Shower room	Inside doors	No access	NA (no access)	No access (Presumption)	NA	NA	NA	NA	NA	NA	NA	NA	Re-evaluate if access obtained	17/11/21			
E				2220AS136A-005	Shower room	Inside vertical boxing	No access	NA (no access)	No access (Presumption)	NA	NA	NA	NA	NA	NA	NA	NA	Re-evaluate if access obtained	17/11/21			
G			00005/B1004-1	2220AS136A-001	Shower room	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/06/19			Previously sampled as negative, refer to 2220AS136-001
G			00005/B1004-2	2220AS136A-002	Shower room	Lining to boxing	Board	Insulating board	Negative asbestos sample	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/06/19			Previously sampled as negative, refer to 2220AS136-002
G			PHH11858-1	2220AS136A-003	Shower room	Floor	Grey vinyl sheet and adhesive	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/06/19			