

13 Glanselsig Terrace, Blaencwm, Treorchy.						Survey Type >				Type 2				Initial Survey Date(s) >			16/12/2009				
2220AS14						Position	Component description	Material	Asbestos ID	Extent / approx quantity	Accessibility	Damage	Surface treatment	Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN	Lab Ref	Site Ref	Area or room									Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation				Last date ACM inspected
G		01GLA01300	91558/B473-1	2220AS14-001	GF - Lounge and front room	Ceilings	'Artex' - 'Fan'	Textured coatings & joint compound	Negative asbestos sample	27SM	NA	NA	NA	NA	NA	NA	No action not an ACM	16/12/09			
G		01GLA01300	91558/B473-2	2220AS14-002	GF - Bathroom, halls 1, 2 and kitchen	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	19SM	NA	NA	NA	NA	NA	NA	No action not an ACM	16/12/09			
G		01GLA01300	91558/B473-3	2220AS14-003	GF - Kitchen	Floor	Dark grey vinyl tiles	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	8SM	NA	NA	NA	NA	NA	NA	No action not an ACM	16/12/09			
G		01GLA01300	91558/B473-4	2220AS14-004	GF - Kitchen	Floor	Mauve vinyl tiles	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	8SM	NA	NA	NA	NA	NA	NA	No action not an ACM	16/12/09			
G		01GLA01300	91558/B473-5	2220AS14-005	GF - Kitchen	Under sink top	Bitumen pad	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	No action not an ACM	16/12/09			
G		01GLA01300	91558/B473-6	2220AS14-006	FF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	32SM	NA	NA	NA	NA	NA	NA	No action not an ACM	16/12/09			
G		01GLA01300	91558/B473-7	2220AS14-007	Roof space	Under roof coverings	Sarking felt	Bitumen roofing felts	Negative asbestos sample	50SM	NA	NA	NA	NA	NA	NA	No action not an ACM	16/12/09			