

| 10 Tyle Fforest, Treherbert, Treorchy. | | | | Survey Type > | | Management | | Initial Survey Date(s) > | | | | | | | 04/08/2022 | | | | | | | |
|--|----------------------------|----------------------|-------------|-----------------|--|---|-----------------------|---|-----------------------------------|--------------------------|------------------|-----------|----------------------|--|--------------------------------|---|-------------------------|---|-------------------------|------------------------|---------------------------|----------------|
| 2220AS1448 | | | | Register Type > | | Final | | Risk ratings | | | | | | | Management Action | | | | | | | |
| Report Section | Extrapolated from Site Ref | UPRN (if applicable) | Lab Ref | Site Ref | Area or room | Position | Component description | Material | Asbestos ID | Extent / approx quantity | ** Accessibility | ** Damage | ** Surface treatment | Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite) | Total Material Risk rating "A" | Total Priority Risk rating "B" - Score breakdown available on request | Total Risk Rating "A+B" |  | Last date ACM inspected | Last date ACM modified | Note | Licensed work? |
| G | | | PHH29 340-1 | 2220AS14 48-001 | Ground floor - All areas | To floor and under some floor coverings | Tiles and adhesive | PVC vinyl flooring and adhesive | Negative asbestos sample | 40SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | | |
| G | | | PHH29 340-2 | 2220AS14 48-002 | Ground floor - All areas except lounge | Ceilings | 'Artex' - 'Stipple' | Textured coatings & joint compound | Negative asbestos sample | 20SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | | |
| G | | | PHH29 340-3 | 2220AS14 48-003 | Ground floor - Lounge | Ceiling | 'Artex' - 'Fan' | Textured coatings & joint compound | Negative asbestos sample | 20SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | | |
| G | | | PHH29 340-7 | 2220AS14 48-007 | First floor - All areas | Ceilings | 'Artex' - 'Stipple' | Textured coatings & joint compound | Negative asbestos sample | 40SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | | |
| H | | | | 2220AS14 48-004 | Ground floor - Kitchen | Under sink | Bitumen pad | Bitumen coatings on metal | Discounted material (not sampled) | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | Not enough left to sample | |
| H | | | | 2220AS14 48-005 | Ground floor - Kitchen | Within boiler | Gaskets | Textiles - Gaskets & washers | Discounted material (not sampled) | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | Valiant | |
| H | | | | 2220AS14 48-006 | Ground floor - Toilet | Behind toilet | Waste pipe | Reinforced plastic and resin composites | Discounted material (not sampled) | 1No | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | | |
| H | | | | 2220AS14 48-008 | First floor - Bathroom | Behind toilet | Waste pipe | Reinforced plastic and resin composites | Discounted material (not sampled) | 1No | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | | |
| H | | | | 2220AS14 48-009 | First floor - Bathroom | Side of bath | Bath side panel | Cardboard | Discounted material (not sampled) | 3LM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | | |
| H | | | | 2220AS14 48-010 | Porch | Gable end undercloak | Lining board | Other | Discounted material (not sampled) | 1LM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/08/22 | | Wood | |

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.