

Bathroom - 98 Gelli Road, Pentre.					Survey Type >		Refurbishment		Initial Survey Date(s) >							13/02/2017						
2220AS202A					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
A			00005/B1134-3	2220AS20 2A-002	Bathroom	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Positive asbestos sample	4SM	NA	0	1	1	3	NA	NA	Remove	13/02/17		Previously sampled as positive, please refer to 2220AS202-006	No*
G			PHH13 21-1	2220AS20 2A-005	Bathroom	Bath panel	Lining board	Insulating board	Negative asbestos sample	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	13/02/17			
H				2220AS20 2A-001	Bathroom	Floor	Grey speckled vinyl sheet	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	13/02/17			
H				2220AS20 2A-003	Bathroom	Walls around bath	Ceramic tiles	Other	Discounted material (not sampled)	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	13/02/17			
H				2220AS20 2A-004	Bathroom	Walls adjacent to landing and bedroom	Lining board	Insulating board	Discounted material (not sampled)	10SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	13/02/17		Plasterboard	

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.