

5 East Street, Tylorstown, Ferndale.					Survey Type >			Management		Initial Survey Date(s) >						11/01/2011					
2220AS226																Management Action					
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings				Last date ACM inspected	Last date ACM modified	Note	Licensed work?
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"					
G	54EA200500	NGA3030-1	2220AS226-001	GF - Kitchen	Under side sink top and drainer	Bitumen pads	Bitumen coatings on metal	Negative asbestos sample	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	11/01/11				
G	54EA200500	NGA3030-2	2220AS226-003	GF - Hall	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	1SM	NA	NA	NA	NA	NA	NA	No action not an ACM	11/01/11				
G	54EA200500	NGA3030-3	2220AS226-004	GF - Lounge and kitchen	Ceilings	'Artex' - 'Circle'	Textured coatings & joint compound	Negative asbestos sample	21SM	NA	NA	NA	NA	NA	NA	No action not an ACM	11/01/11				
G	54EA200500	NGA3030-4	2220AS226-006	FF - All rooms	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	24SM	NA	NA	NA	NA	NA	NA	No action not an ACM	11/01/11				
H	54EA200500		2220AS226-005	GF - Kitchen	Floor	Beige vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	9SM	NA	NA	NA	NA	NA	NA	No action not an ACM	11/01/11				
H	54EA200500		2220AS226-007	Roof space	Under side roof coverings	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	40SM	NA	NA	NA	NA	NA	NA	No action not an ACM	11/01/11				
I	54EA200500		2220AS226-002	GF - Lounge	Within back boiler	Internal gaskets and washers	Textiles - Gaskets & washers	Removed	Small Quants	NA	NA	NA	NA	NA	NA	No action not an ACM	20/06/14				