

2 John Street, Porth.					Survey Type >			Management		Initial Survey Date(s) >						19/01/2011						
2220AS258																						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings			Management Action					
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation				Last date ACM inspected	Last date ACM modified
G			NGA31 28-1	2220AS25 8-003	GF - All areas	Ceilings	'Artex' - 'Comb'	Textured coatings & joint compound	Negative asbestos sample	44SM	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/11				
G			NGA31 28-2	2220AS25 8-006	FF - All areas	Ceilings	'Artex' - 'Comb'	Textured coatings & joint compound	Negative asbestos sample	44SM	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/11				
H				2220AS25 8-001	GF - Kitchen	Underside sink top and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/11				
H				2220AS25 8-002	GF - Kitchen	Floor	Beige sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	15SM	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/11				
H				2220AS25 8-004	GF - Hall and toilet	Floors	Brown sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	8SM	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/11				
H				2220AS25 8-005	FF - Bathroom	Floor	Tile effect sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/11				
H				2220AS25 8-007	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	40SM	NA	NA	NA	NA	NA	NA	No action not an ACM	19/01/11				