

Bathroom - 9 Prospect Place, Tylorstown, Ferndale.				Survey Type >		Refurbishment		Initial Survey Date(s) >							04/07/2018							
2220AS273A				Register Type >		Final		Risk ratings							Management Action							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
A			NGA31 66-3	2220AS27 3A-001	Bathroom	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Positive asbestos sample	4SM	NA	0	1	1	3	NA	NA	Remove	04/07/18		Previously sampled as positive, refer to 2220AS273A-006. Can be left in place if not affected by works.	No*
G			PHH68 17-1	2220AS27 3A-003	Bathroom	Bath panel	Lining board	Insulating board	Negative asbestos sample	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	04/07/18			
H				2220AS27 3A-002	Bathroom	Floor	Beige vinyl sheet	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	04/07/18		Floor boards below vinyl	

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.