

Bathroom - 24 Miles Street, Maerdy, Ferndale.				Survey Type >			Refurbishment		Initial Survey Date(s) >							05/07/2018						
2220AS292A				Register Type >			Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGA34 69-4	2220AS29 2A-001	Bathroom	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	6SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/18		Previously sampled as negative, refer to 2220AS292-005	
G			PHH68 74-1	2220AS29 2A-003	Bathroom	Bath panel	Reinforced plastic	Reinforced plastic and resin composites	Negative asbestos sample	1SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/18			
H				2220AS29 2A-002	Bathroom	Floor covering	Blue vinyl sheet	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	05/07/18			

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.