

179 East Road, Tylorstown, Ferndale.				Survey Type >			Management		Initial Survey Date(s) >						21/02/2011						
2220AS294																					
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings			Management Action				
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"			Last date ACM inspected	Last date ACM modified	Note
G			NGA34 40-1	2220AS29 4-001	LG - Kitchen and understairs cupboard	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	20SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/02/11			
G			NGA34 40-2	2220AS29 4-002	LG - Understair cupboard	Floor	Beige vinyl floor tile	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	3SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/02/11			
G			NGA34 40-3	2220AS29 4-003	LG - Kitchen	Underside sink top	Bitumen pad	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	No action not an ACM	21/02/11			
G			NGA34 40-4	2220AS29 4-004	GF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	56SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/02/11			
H				2220AS29 4-005	GF - Toilet and bathroom	Floors	Blue sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	8SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/02/11			