

Bathroom - 5 Jones Terrace, Treherbert, Treorchy.				Survey Type >		Refurbishment		Initial Survey Date(s) >							27/06/2019								
2220AS316A				Register Type >		Final		Risk ratings							Management Action								
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGA37 36-4	2220AS31 6A-001	Bathroom	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	5SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/06/19			Previously sampled as negative, refer to 2220AS316-005	
G			PHH11 844-1	2220AS31 6A-002	Bathroom	Floor - Beneath laminate	Green vinyl sheet	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/06/19				
H				2220AS31 6A-003	Bathroom	Lining to bath, behind plastic panel	Board	Other	Discounted material (not sampled)	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/06/19				

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.