

12 Ashfield Close, Cymmer Road, Porth.				Survey Type >			Management			Initial Survey Date(s) >						23/03/2011						
2220AS434																Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings				Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"						
G			NGA40 22-1	2220AS43 4-001	Lounge	Ceiling	'Artex' - 'Fan'	Textured coatings & joint compound	Negative asbestos sample	10SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11				
G			NGA40 22-2	2220AS43 4-002	All areas except lounge	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	25SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11				
G			NGA40 22-3	2220AS43 4-003	Porch	Under current flooring	Beige vinyl floor tile	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	1SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11				
H				2220AS43 4-004	Kitchen	Underside sink top and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11				
H				2220AS43 4-005	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	40SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11				

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.