

9 Clos Ynysygrug, Trealaw Road, Trealaw, Tonypandy.				Survey Type >			Management		Initial Survey Date(s) >							28/03/2011					
2220AS443																Management Action					
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings			 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"					
G			NGA40 39-1	2220AS44 3-001	GF - Kitchen	Underside sink top	Bitumen pad	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	No action not an ACM	28/03/11			
G			NGA40 39-2	2220AS44 3-002	GF - Kitchen	Ceiling	'Artex' - 'Random'	Textured coatings & joint compound	Negative asbestos sample	6SM	NA	NA	NA	NA	NA	NA	No action not an ACM	28/03/11			
G			NGA40 39-3	2220AS44 3-003	GF - Understairs cupboard	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	2SM	NA	NA	NA	NA	NA	NA	No action not an ACM	28/03/11			
G			NGA40 39-4	2220AS44 3-004	FF - Bedroom 2	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	10SM	NA	NA	NA	NA	NA	NA	No action not an ACM	28/03/11			
H				2220AS44 3-005	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	40SM	NA	NA	NA	NA	NA	NA	No action not an ACM	28/03/11			
H				2220AS44 3-006	External - Gable end and porch canopy	Undercloak	Lining board	Insulating board	Discounted material (not sampled)	11SM	NA	NA	NA	NA	NA	NA	No action not an ACM	28/03/11			