

Bathroom - 9 Clos Ynysygrug, Trealaw Road, Trealaw.					Survey Type >		Refurbishment		Initial Survey Date(s) >							09/02/2017						
2220AS443B					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			PHH12 05-1	2220AS44 3B-003	Bathroom	Walls behind ceramic tiles	Lining board	Insulating board	Negative asbestos sample	14SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/17			
H				2220AS44 3B-001	Bathroom	Walls and floor	Ceramic tiles	Ceramic	Discounted material (not sampled)	18SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/17			
H				2220AS44 3B-002	Bathroom	Lining board	Bath panel	Insulating board	Discounted material (not sampled)	1SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/17		Plastic cladding	