

15 Sycamore Drive, Trealaw, Tonypanyd.				Survey Type >			Management		Initial Survey Date(s) >							31/03/2011						
2220AS459																Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings				Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"						
G			NGA40 46-1	2220AS45 9-001	GF - Kitchen	Under side of sink	Bitumen pads	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	No action not an ACM	31/03/11				
G			NGA40 46-2	2220AS45 9-002	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Negative asbestos sample	50SM	NA	NA	NA	NA	NA	NA	No action not an ACM	31/03/11				
G			NGA40 46-3	2220AS45 9-004	External	Low level brickwork	D.P.C.	Bitumen damp proof courses	Negative asbestos sample	24LM	NA	NA	NA	NA	NA	NA	No action not an ACM	31/03/11				
H				2220AS45 9-003	GF - Kitchen - FF - Bathroom	Floors	Grey speckled vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	15SM	NA	NA	NA	NA	NA	NA	No action not an ACM	31/03/11				