

Kitchen - 15 Sycamore Drive, Trealaw, Tonypanydy.					Survey Type >		Refurbishment		Initial Survey Date(s) >							29/06/2017						
2220AS459A					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			PHH24 02-1	2220AS45 9A-003	Ground floor - Kitchen	Underside of worktops	Paper lining	Paper inc lining to 'strawboard'	Negative asbestos sample	3SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/17			
H				2220AS45 9A-001	Ground floor - Kitchen	Floor	Wood effect vinyl flooring sheet	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	9SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/17			
H				2220AS45 9A-002	Ground floor - Kitchen	Underside of sink and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/17			