

38 Graig Wen, Maerdy, Ferndale.					Survey Type >			Management		Initial Survey Date(s) >						21/07/2011					
2220AS467																					
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings			Management Action				
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation				Last date ACM inspected
A			NGA45 13-3	2220AS46 7-006	External - Main roof	Undercloak to gable end verges	Lining board	Cement - Fully comp flat sheet, tiles, slates & boards	Positive asbestos sample	11LM	0	0	0	2	1	3	Record, manage & monitor	11/01/24			No*
G			NGA45 13-1	2220AS46 7-001	GF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	36SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/07/11			
G			NGA45 13-2	2220AS46 7-004	FF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	36SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/07/11			
H				2220AS46 7-002	GF - Kitchen and toilet	Floors	Beige sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	8SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/07/11			
H				2220AS46 7-003	GF - Kitchen	Underside sink top	Bitumen pad	Bitumen coatings on metal	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	21/07/11			
H				2220AS46 7-005	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	50SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/07/11			
H				2220AS46 7-007	FF - Bathroom	Floor	Beige sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	No action not an ACM	21/07/11			
I	2220 AS46 7-006			2220AS46 7-008	External - Porch canopy	Undercloak to gable end verges	Lining board	Cement - Fully comp flat sheet, tiles, slates & boards	Removed	3LM	NA	NA	NA	NA	NA	NA	No action not an ACM	17/10/17			Porch removed since previous visit

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.