

20 Oakwood Drive, Thomastown, Porth.					Survey Type >			Management		Initial Survey Date(s) >							09/02/2012					
2220AS592																						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Risk ratings			Management Action				
															Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"			Last date ACM inspected	Last date ACM modified	Note
E				2220AS592-004	GF - Lounge and hall	Under existing laminated flooring	N/A	No access (Presumption)	No access (Presumption)	22SM	NA	NA	NA	NA	NA	NA	NA	Re-evaluate if access obtained	26/07/23		New laminate flooring	
G			NGA6048-1	2220AS592-001	GF - All rooms	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	40SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/12			
G			NGA6048-2	2220AS592-005	FF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	40SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/12			
H				2220AS592-002	GF - Kitchen	Underside sink top	Bitumen pad	Bitumen coatings on metal	Discounted material (not sampled)	1No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/12		New kitchen	
H				2220AS592-003	GF - Kitchen and toilet	Floors	Brown speck sheet vinyl	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	16SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/12			
H				2220AS592-006	FF - Bathroom	Floor	Beige sheet vinyl	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/12			
H				2220AS592-007	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	50SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	09/02/12			

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.