

11 Pendyrus Court, Tylorstown, Ferndale.					Survey Type >			Management		Initial Survey Date(s) >							11/07/2012					
2220AS697																	Management Action					
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** A accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
A			NGA69 69-2	2220AS69 7-006	External - Porch and gable end	Under cloak to verges	Lining board	Insulating board	Positive asbestos sample	12LM	0	0	2	1	5	2	7		Record, manage & monitor	16/01/24		
G			NGA69 69-1	2220AS69 7-001	All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	40SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	11/07/12			
H				2220AS69 7-002	Kitchen	Floor	Beige vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	6SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	11/07/12			
H				2220AS69 7-003	Kitchen	Under side of sink	Bitumen pad	Bitumen coatings on metal	Discounted material (not sampled)	1No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	11/07/12			
H				2220AS69 7-004	Bathroom	Floor	Red vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	6SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	11/07/12			
H				2220AS69 7-005	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material	50SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	11/07/12			

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.