

Bathroom - 36 Lllys Catwg, New Park, Talbot Green, Pontyclun.					Survey Type >		Refurbishment		Initial Survey Date(s) >							07/02/2017							
2220AS771A					Register Type >		Final		Risk ratings							Management Action							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGAR0 0429-1	2220AS77 1A-002	Bathroom	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	07/02/17			Previously sampled as negative 2220AS771-001	
G			PHH12 10-1	2220AS77 1A-004	Bathroom	Walls and boxing	Lining board	Insulating board	Negative asbestos sample	14SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	07/02/17				
H				2220AS77 1A-001	Bathroom	Floor	Grey sheet vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	6SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	07/02/17				
H				2220AS77 1A-003	Bathroom	walls around shower	Ceramic tiles	Other	Discounted material (not sampled)	7SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	07/02/17			Ceramic	