

21 Griffiths Street, Maerdy, CF43 4DH.				Survey Type >		Asbestos Sample Only (No Survey)		Initial Survey Date(s) >						11/01/2012								
2220AS797														Management Action								
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	(1 Asbestos type = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Risk ratings			Management Action				
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	PHH ENVIRONMENTAL Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?	
A			NGA73 09-1	2220AS79 7-001	External - Rear yard	Debris to floor	Cement debris	Cement - Profiled sheets	Positive asbestos sample	Small Quants	1	2	0	1	4	4	8	Remove	11/01/12		Debris throughout garden and buried in planting area	No*

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.