

Bathroom - 26 Graig Wen, Maerdy, Ferndale.					Survey Type >		Refurbishment		Initial Survey Date(s) >							06/02/2017						
2220AS925A					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGAR01580-2	2220AS925A-002	Bathroom	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	06/02/17		Previously sampled as negative please refer to 2220AS925-006	
G			PHH1211-1	2220AS925A-005	Bathroom	Walls adjacent to bedroom, landing and cupboard	Lining board	Insulating board	Negative asbestos sample	8SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	06/02/17			
H				2220AS925A-001	Bathroom	Floor	Wood effect vinyl sheet flooring	Thermoplastic floor tiles	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	06/02/17			
H				2220AS925A-003	Bathroom	Walls around bath	Ceramic tiles	Other	Discounted material (not sampled)	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	06/02/17			
H				2220AS925A-004	Bathroom	Under current flooring	Grey vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	06/02/17			