

23 Victoria Street, Treherbert, Treorchy.				Survey Type >			Management		Initial Survey Date(s) >						29/06/2010							
2220AS94															Management Action							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	* Accessibility	* Damage	* Surface treatment	Risk ratings				Last date ACM inspected	Last date ACM modified	Note	Licensed work?	
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"						Recommendation
G			00005/B729-1	2220AS94-001	GF - Kitchen	Under side of sink top	Bitumen pad	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/10				
G			00005/B729-2	2220AS94-002	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Negative asbestos sample	40SM	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/10				

* risk assessment required prior to work/Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.