

Bathroom - 16 Pentre Road, Maerdy, Ferndale.					Survey Type >		Refurbishment		Initial Survey Date(s) >							15/02/2017						
2220AS953B					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGAR01708-6	2220AS953B-002	Bathroom	Ceiling	'Artex' - 'Shell'	Textured coatings & joint compound	Negative asbestos sample	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	15/02/17		Previously sampled as negative, please refer to 2220AS953-010	
G			PHH1341-1	2220AS953B-005	Bathroom	Bath panel behind tongue and groove cladding	Lining board	Insulating board	Negative asbestos sample	1SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	15/02/17			
H				2220AS953B-001	Bathroom	Floor	Grey tile effect vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	15/02/17			
H				2220AS953B-003	Bathroom	Walls around bath	Ceramic tiles	Other	Discounted material (not sampled)	13SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	15/02/17		Ceramic	
H				2220AS953B-004	Bathroom	Walls	Lining board	Insulating board	Discounted material (not sampled)	13SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	15/02/17			
H				2220AS953B-006	Bathroom	Under current flooring	Grey speckled vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	15/02/17			
H				2220AS953B-007	Bathroom	Boxing behind sink and toilet	Boxing board	Insulating board	Discounted material (not sampled)	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	15/02/17		Plywood	

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.