

107 Meadow Rise, Brynna, Pontyclun.				Survey Type >		Asbestos Sample Only (No Survey)		Initial Survey Date(s) >				25/06/2018											
2220S1289				Register Type >		Final						Risk ratings		Management Action									
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"			Last date ACM inspected	Last date ACM modified	Note	Licensed work?
I			PHH6651-1	2220S1289-001	External bow window	Lounge	Lining board	Insulating board	Removed	2LM	0	1	2	2	7	2	9	No action not an ACM	25/06/18		Removed November 2018	Yes	

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.