Kitchen - 2 Clos Ynysgrug, Trealaw Road, Trealaw, Tonypandy.						Survey Type >		Refurbishment											Initial Survey Date(s) >	29/06/2016			
2220AS853A						Register Type >		Final							Risk ratings				Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGAR01454-2	2220AS853A-004	Kitchen	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	9SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/16		Previously sampled as negative please refer to management report 2220AS853-004.	
G			NGAR7816-1	2220AS853A-006	Kitchen	Under all vinyl sheet flooring and screed	Grey tiles and adhesive	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	9SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/16			
H				2220AS853A-001	Kitchen	Floor	Grey tile effect vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	9SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/16			
H				2220AS853A-002	Kitchen	Under current flooring	Salmon coloured speckled vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	9SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/16			
H				2220AS853A-003	Kitchen	Walls above worktops	Ceramic tiles	Ceramic	Discounted material (not sampled)	3SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/16			
H				2220AS853A-005	Kitchen	Within wall mounted boiler	Gaskets	Textiles - Gaskets & washers	Discounted material (not sampled)	Small Quants	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	29/06/16		New Vaillant boiler	