

| Kitchen - 86 Corbett Street, Treherbert, Treorchy. | | | | Survey Type > | | Refurbishment | | Initial Survey Date(s) > | | | | | | | 31/05/2022 | | | | | | | |
|--|----------------------------|----------------------|-------------|------------------|--------------|---------------|----------------------------|---|-----------------------------------|--------------------------|------------------|-----------|----------------------|--|--------------------------------|---|-------------------------|---|-------------------------|------------------------|------|---|
| 2220AS1329A | | | | Register Type > | | Final | | Risk ratings | | | | | | | Management Action | | | | | | | |
| Report Section | Extrapolated from Site Ref | UPRN (if applicable) | Lab Ref | Site Ref | Area or room | Position | Component description | Material | Asbestos ID | Extent / approx quantity | ** Accessibility | ** Damage | ** Surface treatment | Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite) | Total Material Risk rating "A" | Total Priority Risk rating "B" - Score breakdown available on request | Total Risk Rating "A+B" |  | Last date ACM inspected | Last date ACM modified | Note | Licensed work? |
| G | | | PHH28 069-1 | 2220AS13 29A-002 | Kitchen | Doorway | Beige tiles and adhesive | PVC vinyl flooring and adhesive | Negative asbestos sample | 1SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 31/05/22 | | | |
| G | | | PHH28 069-2 | 2220AS13 29A-003 | Kitchen | Ceiling | 'Artex' - 'Stipple' | Textured coatings & joint compound | Negative asbestos sample | 12SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 31/05/22 | | | Bubbling and peeling around boiler pipe |
| G | | | PHH28 069-3 | 2220AS13 29A-004 | Kitchen | Under sink | Bitumen pad | Bitumen coatings on metal | Negative asbestos sample | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 31/05/22 | | | |
| H | | | | 2220AS13 29A-001 | Kitchen | Floor | Beige sheet vinyl flooring | PVC vinyl floor tiles & unbacked PVC flooring | Discounted material (not sampled) | 12SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 31/05/22 | | | |
| H | | | | 2220AS13 29A-005 | Kitchen | Within boiler | Gaskets | Textiles - Gaskets & washers | Discounted material (not sampled) | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 31/05/22 | | | Worcester |

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.