

97 Dunraven Street, Tonypanydy.				Survey Type >		Asbestos Sample Only (No Survey)		Initial Survey Date(s) >						31/01/2019									
2220AS1386				Register Type >		Final		Risk ratings						Management Action									
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			PHH94 13-1	2220AS13 86-001	External	Roof covering	Cement slate	Cement - Fully comp flat sheet, tiles, slates & boards	Negative asbestos sample	70SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	31/01/19				

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.