

6 Volunteer Street, Pentre.				Survey Type >			Management		Initial Survey Date(s) >						13/01/2011						
2220AS244																					
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings			Management Action				
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation				Last date ACM inspected
G			NGA30 46-1	2220AS24 4-001	GF - Kitchen	Underside sink top and drainer	Bitumen pads	Bitumen coatings on metal	Negative asbestos sample	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	13/01/11			
H				2220AS24 4-002	GF - Kitchen	Floor	Black cushion Flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	9SM	NA	NA	NA	NA	NA	NA	No action not an ACM	13/01/11			
I				2220AS24 4-003	GF - Lounge/dinner	Within gas fire back boiler	Gaskets	Textiles - Gaskets & washers	Removed	1No	NA	NA	NA	NA	NA	NA	No action not an ACM	11/08/14		Fire condemned but still in place 18/10/2013	