

4 Ashfield Close, Cymmer Road, Porth.				Survey Type >			Management		Initial Survey Date(s) >						23/03/2011						
2220AS436															Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings				Last date ACM inspected	Last date ACM modified	Note	Licensed work?
														Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"					
G			NGA40 21-1	2220AS43 6-001	GF - Lounge	Ceiling	'Artex'- 'Fan'	Textured coatings & joint compound	Negative asbestos sample	14SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11			
G			NGA40 21-2	2220AS43 6-002	GF - All areas except lounge	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	28SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11			
G			NGA40 21-3	2220AS43 6-003	FF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	32SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11			
H				2220AS43 6-004	GF - Kitchen	Underside sink top and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11			
H				2220AS43 6-005	GF - Kitchen and FF - Bathroom	Floors	beige speckled sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	11SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11			
H				2220AS43 6-006	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	36SM	NA	NA	NA	NA	NA	NA	No action not an ACM	23/03/11			