

39 Clos Ynysygrug, Trealaw Road, Trealaw, Tonypanyd.					Survey Type >			Management		Initial Survey Date(s) >							30/03/2011					
2220AS456																	Management Action					
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGA40 33-2220A S456-001	2220AS456-001	GF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	32SM	NA	NA	NA	NA	NA	NA	No action not an ACM	30/03/11				
G			NGA40 33-2220A S456-002	2220AS456-002	FF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	32SM	NA	NA	NA	NA	NA	NA	No action not an ACM	30/03/11				
G			NGA40 33-2220A S456-004	2220AS456-004	FF - Bathroom	Wall	'Artex' - 'Trowelled'	Textured coatings & joint compound	Negative asbestos sample	6SM	NA	NA	NA	NA	NA	NA	No action not an ACM	30/03/11				
H				2220AS456-003	GF - Kitchen	Underside sink top and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	2SM	NA	NA	NA	NA	NA	NA	No action not an ACM	30/03/11				
H				2220AS456-005	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	36SM	NA	NA	NA	NA	NA	NA	No action not an ACM	30/03/11				