

1 Llewellyn Street, Blaencwm, Treorchy.						Survey Type >		Type 2		Initial Survey Date(s) >						15/12/2009					
2220AS7						Position	Component description	Material	Asbestos ID	Extent / approx quantity	Accessibility	Damage	Surface treatment	Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN	Lab Ref	Site Ref	Area or room									Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation				Last date ACM inspected
G		01LLE0 0100	91588/B491-1	2220AS7-001	GF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	41SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09			
G		01LLE0 0100	91588/B491-2	2220AS7-002	GF - Kitchen, utility and under stairs cupboard	Floors	Mauve vinyl tiles	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	14SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09			
G		01LLE0 0100	91588/B491-3	2220AS7-003	GF - Kitchen	Under sink top and drainer	Bitumen pads	Bitumen coatings on metal	Negative asbestos sample	2No	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09			
G		01LLE0 0100	91588/B491-4	2220AS7-004	FF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	34SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09			
G		01LLE0 0100	91588/B491-5	2220AS7-005	Roof space	Under roof coverings	Sarking felt	Bitumen roofing felts	Negative asbestos sample	50SM	NA	NA	NA	NA	NA	NA	No action not an ACM	15/12/09			