

| 6 Rhys Watkin Court, Eleanor Street, Tonypanyd. | | | | Survey Type > | | | Management | | Initial Survey Date(s) > | | | | | | 24/09/2010 | | | | | | | |
|---|----------------------------|----------------------|---------------|---------------|--------------|----------|-----------------------|------------------|--------------------------|--------------------------|-----------------|----------|---------------------|--------------------------------|--------------------------------|-------------------------|---|----------------|-------------------------|------------------------|------|----------------|
| 2222AS182 | | | | | | | | | | | | | | | Management Action | | | | | | | |
| Report Section | Extrapolated from Site Ref | UPRN (if applicable) | Lab Ref | Site Ref | Area or room | Position | Component description | Material | Asbestos ID | Extent / approx quantity | * Accessibility | * Damage | * Surface treatment | Risk ratings | | |  | Recommendation | Last date ACM inspected | Last date ACM modified | Note | Licensed work? |
| | | | | | | | | | | | | | | Total Material Risk rating "A" | Total Priority Risk rating "B" | Total Risk Rating "A+B" | | | | | | |
| G | | | 00005/B1065-1 | 2222AS182-001 | Bathroom | Boxing | Boxing board | Insulating board | Negative asbestos sample | 3LM | NA | NA | NA | NA | NA | NA | No action not an ACM | 24/09/10 | | | | |

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.