

| 3 Constantine Court, Constantine Street, Williamstown, Tonypandy. | | | | Survey Type > | | | Management | | Initial Survey Date(s) > | | | | | | | 02/06/2023 | | | | | | |
|---|----------------------------|----------------------|-------------|-----------------|--------------|----------------|----------------------------|---|-----------------------------------|--------------------------|------------------|-----------|----------------------|--|--------------------------------|---|-------------------------|--|-------------------------|------------------------|------|----------------|
| 2220AS1555 | | | | Register Type > | | | Final | | Risk ratings | | | | | | | Management Action | | | | | | |
| Report Section | Extrapolated from Site Ref | UPRN (if applicable) | Lab Ref | Site Ref | Area or room | Position | Component description | Material | Asbestos ID | Extent / approx quantity | ** Accessibility | ** Damage | ** Surface treatment | Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite) | Total Material Risk rating "A" | Total Priority Risk rating "B" - Score breakdown available on request | Total Risk Rating "A+B" |  Recommendation | Last date ACM inspected | Last date ACM modified | Note | Licensed work? |
| G | | | PHH35 234-1 | 2220AS15 55-001 | All areas | Ceilings | 'Artex' - 'Stipple' | Textured coatings & joint compound | Negative asbestos sample | 34SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |
| G | | | PHH35 234-2 | 2220AS15 55-002 | Kitchen | Under sink | Bitumen pad | Bitumen coatings on metal | Negative asbestos sample | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |
| G | | | PHH35 234-3 | 2220AS15 55-005 | Bathroom | Next to sink | Boxing | Insulating board | Negative asbestos sample | 3SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |
| H | | | | 2220AS15 55-003 | Kitchen | Floor | Brown sheet vinyl flooring | PVC vinyl floor tiles & unbacked PVC flooring | Discounted material (not sampled) | 4SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |
| H | | | | 2220AS15 55-004 | Kitchen | Around worktop | Mastic | Bitumen mastic, caulking & putty | Discounted material (not sampled) | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |
| H | | | | 2220AS15 55-006 | Bathroom | Floor | White sheet vinyl flooring | PVC vinyl floor tiles & unbacked PVC flooring | Discounted material (not sampled) | 4SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |
| H | | | | 2220AS15 55-007 | Bathroom | Behind toilet | Waste pipe | Reinforced plastic and resin composites | Discounted material (not sampled) | 1No | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |
| H | | | | 2220AS15 55-008 | Bathroom | Around sink | Mastic | Bitumen mastic, caulking & putty | Discounted material (not sampled) | Small Quants | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 02/06/23 | | | |

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.