

Kitchen - 64 Jones Street, Blaenclydach, Tonypandy.					Survey Type >		Refurbishment		Initial Survey Date(s) >							03/07/2016						
2220AS1012B					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGAR0 2201-2	2220AS10 12B-001	Kitchen	Underside of sink and drainer	Bitumen pads	Bitumen coatings on metal	Negative asbestos sample	2No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	03/07/16		Previously sampled as negative, please refer to 2220AS1012-003	
G			PHH24 20-1	2220AS10 12B-004	Kitchen	Underside of worktops	Paper lining	Paper inc lining to 'strawboard'	Negative asbestos sample	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	03/07/16			
H				2220AS10 12B-002	Kitchen	Floor	Grey vinyl flooring sheet	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	8SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	03/07/16			
H				2220AS10 12B-003	Kitchen	Walls above worktops	Ceramic tiles	Ceramic	Discounted material (not sampled)	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	03/07/16			