
All areas 2220AS122 - 002



2220AS122 - 004

Roof spaces 1 and 2 2220AS122 – 003

External – Path wall in front garden 2220AS122 - 001

Hallway 2220AS122 - 005

Site reference points colour coding:

RED for 'positive', 'strongly presumed', 'presumed' and 'contaminated' ACMs

**BLUE** for 'Presumed to contain ACMs due to no access'

GREEN for 'discounted materials', 'no asbestos suspected' and 'negative BLACK for 'removed' ACMs

Do not scale, not dimensionally accurate

## Note:

This must be reproduced in colour and is to be read in conjunction with the full report.



Annex III Project Ref. 2220AS122
Flat 77a Clydach Road, Blaenclydach,
TonypandyPage **1** of **1**