23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey										Initial Survey Date(s) >				14/11/2014			
2220AS1261															Risk ratings				Management Action						
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
C				2220AS1261-009	External	Roof covering	Slate	Cement - Fully comp flat sheet, tiles, slates & boards	Presumption	35SM	0	0	1	1	3	1	4	Record, manage & monitor	12/01/24		Too high to sample.	No*
G			NGAR04143-1	2220AS1261-003	GF - All areas	Floors and under current floorings	Beige tile and adhesive	PVC vinyl floor tiles & unbacked PVC flooring	Negative asbestos sample	30SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			
G			NGAR04143-2	2220AS1261-004	GF - All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	30SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			
G			NGAR04143-3	2220AS1261-007	FF - All areas except cupboard	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	29SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			
H				2220AS1261-001	GF - Kitchen	Under sink	Bitumen pad	Bitumen coatings on metal	Discounted material (not sampled)	1No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			
H				2220AS1261-002	GF - Kitchen	Floor	Laminate sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	14SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			
H				2220AS1261-005	GF - Hall	Floor	Self stick tiles	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	3SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			
H				2220AS1261-006	FF - Bathroom	Floor	Beige sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	3SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			
H				2220AS1261-008	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	35SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	14/11/14			

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings			Management Action				
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?

** see tables 2.2 and 2.3 in Report for definitions

23 Oxford Street, Maerdy.						Survey Type >		Update Asbestos Survey									Initial Survey Date(s) >	14/11/2014			
2220AS1261														Risk ratings				Management Action			
Report Section	Extrapolated from Site Ref	UPRN (If applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?