

| Kitchen - 39 De Barri Street, Rhydyfelin, Pontypridd. | | | | | Survey Type > | | Refurbishment | | Initial Survey Date(s) > | | | | | | | 04/07/2017 | | | | | | | |
|---|----------------------------|----------------------|------------|-----------------|------------------------|--------------------------|-----------------------|---|-----------------------------------|--------------------------|------------------|-----------|----------------------|--|--------------------------------|---|-------------------------|--|-------------------------|------------------------|------|----------------|--|
| 2220AS1374 | | | | | Register Type > | | Final | | Risk ratings | | | | | | | Management Action | | | | | | | |
| Report Section | Extrapolated from Site Ref | UPRN (if applicable) | Lab Ref | Site Ref | Area or room | Position | Component description | Material | Asbestos ID | Extent / approx quantity | ** Accessibility | ** Damage | ** Surface treatment | Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite) | Total Material Risk rating "A" | Total Priority Risk rating "B" - Score breakdown available on request | Total Risk Rating "A+B" |  Recommendation | Last date ACM inspected | Last date ACM modified | Note | Licensed work? | |
| G | | | PHH24 34-1 | 2220AS13 74-004 | Ground floor - Kitchen | Ceiling | 'Artex' - Stipple' | Textured coatings & joint compound | Negative asbestos sample | 15SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/07/17 | | | | |
| H | | | | 2220AS13 74-001 | Ground floor - Kitchen | Under side of sink | Bitumen pad | Bitumen coatings on metal | Discounted material (not sampled) | 1No | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/07/17 | | | | |
| H | | | | 2220AS13 74-002 | Ground floor - Kitchen | Under laminated flooring | Beige vinyl tiles | PVC vinyl floor tiles & unbacked PVC flooring | Discounted material (not sampled) | 15SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/07/17 | | | | |
| H | | | | 2220AS13 74-003 | Ground floor - Kitchen | Walls above work tops | Ceramic tiles | Other | Discounted material (not sampled) | 3SM | NA | NA | NA | NA | NA | NA | NA | No action not an ACM | 04/07/17 | | | Ceramic | |

* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.