

Kitchen - 41 Ty Ddewi, St Davids Close, Ton Pentre, Pentre.					Survey Type >		Refurbishment		Initial Survey Date(s) >							16/07/2025						
2220AS1517A					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
A			PHH48 333-1	2220AS15 17A-001	Kitchen	Ceiling	'Artex' - 'Stipple'	Textured coatings & joint compound	Positive asbestos sample	4SM	NA	0	1	1	3	NA	NA	Remove	16/07/25		Can be left in place if not affected by proposed works	No*
H				2220AS15 17A-002	Kitchen	Vertical boxing	Lining board	Insulating board	Discounted material (not sampled)	3LM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	16/07/25		Supalux boxing	
H				2220AS15 17A-003	Kitchen	Under sink and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	Small Quants	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	16/07/25			
H				2220AS15 17A-004	Kitchen	Floor covering	Grey sheet vinyl	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	16/07/25		On to concrete	
H				2220AS15 17A-005	Kitchen	Within Vaillant boiler	Gaskets	Textiles - Gaskets & washers	Discounted material (not sampled)	Small Quants	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	16/07/25			

\* risk assessment required prior to work.

Where 'Carry Out Repairs', 'Seal', 'Encapsulate' or 'Enclose' is recommended, it is implicit that the ACM is also classified as 'Record, Manage and Monitor'.