
All ground floor -Ceilings 008



Site reference points colour coding:

RED for 'positive', 'strongly presumed', 'presumed' and 'contaminated' ACMs

**BLUE** for 'Presumed to contain ACMs due to no access'

GREEN for 'discounted materials', 'no asbestos suspected' and 'negative BLACK for 'removed' ACMs

Do not scale, not dimensionally accurate

## Note:

This must be reproduced in colour and is to be read in conjunction with the full report.



Annex III Project Ref. 2220AS1538
7 Llys Yr Onnen, Mountain Ash
Ground floor plan
Page 1 of 1