

11 Constantine Court, Constantine Street, Williamstown, Tonypanydy.				Survey Type >				Management				Initial Survey Date(s) >				19/04/2023							
2220AS1542				Register Type >				Final				Risk ratings				Management Action							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?	
G			E-35654/1-1	2220AS1542-001	Kitchen	Next to sink	Vertical boxing	Insulating board	Negative asbestos sample	2LM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/04/23				
G			E-35654/1-2	2220AS1542-002	Bathroom	Next to sink	Boxing	Insulating board	Negative asbestos sample	3SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/04/23				
G			E-35654/1-3	2220AS1542-003	All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	34SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/04/23				
H				2220AS1542-004	Kitchen	Floor	Grey sheet vinyl flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	5SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/04/23				
H				2220AS1542-005	Kitchen	Under sink	Bitumen pad	Bitumen coatings on metal	Discounted material (not sampled)	Small Quants	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/04/23				
H				2220AS1542-006	Bathroom	Behind toilet	Waste pipe	Reinforced plastic and resin composites	Discounted material (not sampled)	1No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/04/23				
H				2220AS1542-007	Bathroom	Around sink	Mastic	Bitumen mastic, caulking & putty	Discounted material (not sampled)	Small Quants	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	19/04/23				