

28 Constantine Court, Constantine Street, Williamstown, Tonypanydy.				Survey Type >		Management		Initial Survey Date(s) >							28/04/2023							
2220AS1640				Register Type >		Final		Risk ratings							Management Action							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 PHH ENVIRONMENTAL Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			PHH34 747-1	2220AS16 40-001	All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	50SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	28/04/23		On to plasterboard	
G			PHH34 747-2	2220AS16 40-002	Kitchen and lounge	Boxings	Lining board	Insulating board	Negative asbestos sample	3LM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	28/04/23			
H				2220AS16 40-003	Kitchen	Under sink and drainer	Bitumen pads	Bitumen coatings on metal	Discounted material (not sampled)	Small Quants	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	28/04/23			
H				2220AS16 40-004	Kitchen and bathroom	Floor coverings	Sheet vinyl floorings	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	8SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	28/04/23			
H				2220AS16 40-005	Roof space	Underside of roof	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	60SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	28/04/23			
H				2220AS16 40-006	Roof space	Underside of roof	Lining board panel	Insulating board	Discounted material (not sampled)	1SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	28/04/23		Supalux panel	