

Flat 6 Cwrt Saron, Caroline Street, Williamstown, Tonypanydy.				Survey Type >		Management		Initial Survey Date(s) >							27/09/2010									
2220AS169								Risk ratings							Management Action									
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	* Accessibility	* Damage	* Surface treatment	Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation				Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G	19CWR0 0699	00005/B1063-1	2220AS16 9-001	All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Negative asbestos sample	45SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/09/10						
G	19CWR0 0699	00005/B1063-2	2220AS16 9-004	Kitchen	Underside sink top	Bitumen pad	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/09/10						
G	19CWR0 0699	NGAR 03431-001	2220AS16 9-005	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Negative asbestos sample	48SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/06/14			Sampled as negative 27/06/2014			
H	19CWR0 0699		2220AS16 9-002	Bathroom	Floor	White vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	3SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/09/10						
H	19CWR0 0699		2220AS16 9-003	Kitchen	Floor	White vinyl sheet flooring	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	8SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	27/09/10						