

Kitchen - 26 Heol Seward, Beddau, Pontypridd.					Survey Type >		Refurbishment		Initial Survey Date(s) >							03/07/2017						
2220AS418A					Register Type >		Final		Risk ratings							Management Action						
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Total Material Risk rating "A"	Total Priority Risk rating "B" - Score breakdown available on request	Total Risk Rating "A+B"	 Recommendation	Last date ACM inspected	Last date ACM modified	Note	Licensed work?
A			PHH24 27-1	2220AS41 8A-001	Ground floor - Kitchen	Under ceramic tiles	Bitumen adhesive	Bitumen adhesive & paints	Positive asbestos sample	11SM	NA	0	0	1	2	NA	NA	Remove	03/07/17		Can be left in place if not affected by works to be carried out.	No
H				2220AS41 8A-002	Ground floor - Kitchen	Ceramic tiles	Floor	Ceramic	Discounted material (not sampled)	11SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	03/07/17			
H				2220AS41 8A-003	Ground floor - Kitchen	Walls above workpads	Ceramic tiles	Ceramic	Discounted material (not sampled)	2SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	03/07/17			