

7 Carn y Celyn, Penygraig, Tonypanyd.				Survey Type >			Management		Initial Survey Date(s) >						24/03/2011							
2220AS427															Management Action							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** Accessibility	** Damage	** Surface treatment	Risk ratings			Management Action					
													Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	 Recommendation			Last date ACM inspected	Last date ACM modified	Note	Licensed work?
G			NGA40 13-1	2220AS42 7-001	Kitchen	Underside sink	Bitumen pad	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	No action not an ACM	24/03/11				
G			NGA40 13-2	2220AS42 7-002	Bedroom 2, bathroom, hall and kitchen	Ceilings	' Artex ' - ' Stipple '	Textured coatings & joint compound	Negative asbestos sample	32SM	NA	NA	NA	NA	NA	NA	No action not an ACM	24/03/11				
G			NGA40 13-3	2220AS42 7-003	Lounge and bedroom 1	Ceilings	' Artex ' - ' Comb '	Textured coatings & joint compound	Negative asbestos sample	24SM	NA	NA	NA	NA	NA	NA	No action not an ACM	24/03/11				
H				2220AS42 7-004	Bathroom	Floor	Grey self stick tile	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	6SM	NA	NA	NA	NA	NA	NA	No action not an ACM	24/03/11				
H				2220AS42 7-005	Roof space	Under roof covering	Sarking Felt	Bitumen roofing felts	Discounted material (not sampled)	50SM	NA	NA	NA	NA	NA	NA	No action not an ACM	24/03/11				